

Poor Driver Side Cooling

- CONDITION:** The air conditioning system blows 10 degrees cooler on the passenger side in comparison the driver side. No codes detected.
- CAUSE:** Low Refrigerant – field reports indicate a loss of 20% from the manufacturer’s refrigerant specification could cause this situation.
- CORRECTION:** The vehicle A/C system was checked for leaks and repaired (if any leaks were discovered). The remaining A/C system refrigerant was recovered, the system evacuated and then recharged to manufacturer’s specification. An A/C system performance test was performed. Problem solved.

Product Group	Assembly	Category
Heat & Air Conditioning	Refrigerant	Troubleshooting
Year	Make	Model
2008	Scion	XB