

Radiator Overflow Nipple Cracked

- CONDITION:** After underhood vehicle repairs (belt replacement, leaking radiator, etc.), the radiator overflow nipple is cracked. No codes detected.
- CAUSE:** Field reports indicate that during underhood vehicle repairs, fender covers are removed or not used and excessive force, including body weight, is applied to the overflow nipple.
- CORRECTION:** It is advisable to utilize vehicle fender covers and take extra precaution to prevent exposing the radiator overflow nipple to any excessive force, including body weight.

| Product Group | Assembly | Category |
|----------------------|-----------------|-------------------|
| Cooling System | Radiator | Repair Procedures |
| Year | Make | Model |
| 2007 | Lexus | LS460 |