

A/C Clutch Inoperative and A/C Light Flashing. Check the Magnetic Clutch Relay.

- CONDITION:** The vehicle A/C is inoperative, compressor clutch will not engage and A/C light is flashing.
- CAUSE:** The magnetic clutch relay is disengaging, causing the clutch to disengage and the A/C light to flash.
- CORRECTION:** Toyota has developed a new magnetic clutch relay for this application*.

Original Relay
Revised Relay

Toyota P/N = 90987-02022
Toyota P/N = 90987-02028

DENSO P/N = 156700-2470
DENSO P/N = 156700-3290

If the vehicle is exhibiting the symptoms previously described and the relay Toyota P/N is 90987-02022, replace it with a new relay (Toyota P/N 90987-02028).

*May also be seen in various models which have similar system configurations (e.g. 2002-2004 Toyota Camry; 2001-2004 Toyota Echo; 2001-2004 Toyota Celica; 2002-2004 Toyota 4Runner; 2002-2004 Toyota Corolla; 2003-2004 Toyota Highlander; 2003-2004 Toyota Matrix; 2003-2004 Toyota Sienna; 2003-2004 Toyota Solara).

Product Group	Assembly	Category
Electrical Switches & Relays	Magnetic Clutch Relay	Repair Procedures
Year	Make	Model
2001*	Toyota	Camry*